RG104 E-1 Box 125 January 1882

Mint of the United States at Philadelphia, Pa..

COINER'S DEPARTMENT.

January 5th, 1882.

Hon. A. Loudon Snowden,

Superintendent.

Sir, I have the honor to call your attention to the condition of No 2 Coining Press. The beam, bridles, pins and other working parts are badly in need of repairing, if not renewing. Indeed I think it would be the best economy to introduce a steel beam in place of attempting to patch up the present brass one.

The whole Press requires a thorough overhauling, and it will take considerable time to do it. In view of the quantity of work required of this size Press, I would respectfully recommend that competent parties outside of the Mint, be directed to repair and refit this Press.

Very Respectfully
Yr. Obt Servant
Ob. Bosbyshell
Coiner.

RG104 E-1 Box 125 January 1882

19.

Mint of the United States at Philadelphia, Pa.,

COINER'S DEPARTMENT,

January 5, 1882

O. C. Bosbyshell

Coiner.

Coining Press, No. 2.
needs Stamps
Repairs & outside
pantries)

No. of Enclosures,

Rec'd - Jan. 5th 1882.

NARA RG104, Entry 1, Box 125

[Abstract:] Coining Press, No. 2, needs thorough repairs by outside parties. 19

Mint of the United States at Philadelphia, Pa.,
Coiner's Department,
January 5, 1882

Hon. A. Loudon Snowden,
Superintendent.

Sir;

I have the honor to call your attention to the condition of No. 2 Coining Press. The beam, bridles, pins and other working parts are badly in need of repairing, if not renewing. Indeed I think it would be the best economy to introduce a steel beam in place of attempting to patch up the present brass one.

The whole Press requires a thorough overhauling, and it will take considerable time to do it. In view of the quantity of work required of this size Press, I would respectfully recommend that competent parties outside of the Mint, be directed to repair and refit this Press.

Very Respectfully,
Yr. Obt. Servant
O.C. Bosbyshell
Coiner